

STAIN TREATMENT

SUMMER IS THE WORST TIME TO PERFORM THIS PROCEDURE DUE TO THE POSSIBLE FORMATION OF ALGAE WITH LOW CHLORINE

MINOR STAIN TREATMENT (20,000 GALLONS)

- LOWER CHLORINE BELOW 0.3 PPM (IF NOT ADD **REVERSE** AS NEEDED)
 - ADD A CONTAINER **A+ Stain Remover** AROUND POOL (MUST BRUSH POOL)
 - WATER MAY CLOUD OVER
 - 1 LITER OF **METAL OUT PLUS** (AROUND POOL NOT IN THE SKIMMER)
 - ADD **PURFIBER** INTO THE SKIMMER TO ENHANCE FILTRATION (AMOUNT IS DETERMINED BY FILTER TYPE AND SIZE)
 - RUN POOL NON-STOP UNTIL WATER CLEARS (THIS MAY TAKE SEVERAL DAYS)
 - MUST WAIT AT LEAST **36 HRS** BEFORE ADDING ANY CHLORINE SHOCK
 - ***IF YOU SEE IMPROVEMENT BUT NOT 100% CLEAR REPEAT STAIN TREATMENT***
-

MAJOR STAINS (20,000 GALLONS)

- LOWER CHLORINE BELOW 0.3 PPM (IF NOT ADD **CHLORINE ELIMINATOR** AS NEEDED)
 - ADD TWO CONTAINERS OF **A+ Stain Remover** AROUND POOL (MUST BRUSH POOL)
 - WATER MAY CLOUD OVER
 - 1 LITER OF **METAL OUT PLUS** (AROUND POOL NOT IN THE SKIMMER)
 - ADD **PURFIBER** INTO THE SKIMMER TO ENHANCE FILTRATION (AMOUNT IS DETERMINED BY FILTER TYPE AND SIZE)
 - RUN POOL NON-STOP UNTIL WATER CLEARS (THIS MAY TAKE SEVERAL DAYS)
 - MUST WAIT AT LEAST **36 HRS** BEFORE ADDING ANY CHLORINE SHOCK
 - ***IF YOU SEE IMPROVEMENT BUT NOT 100% CLEAR REPEAT STAIN TREATMENT***
-

***IF NO IMPROVEMENT HAS BEEN MADE USE A STAIN ID KIT**

NOTES:

CONSIDER THE USE OF NON-CHLORINE SHOCK, IF YOU HAVE A REOCCURRING STAINS OR METAL ISSUES NEVER ADD TABS OR STICKS TO SKIMMER IF THERE IS A HATER ON THE POOL. DO NOT SHOCK FOR A LEAST 1 WEEK AFTER TREATMENT. ADD ANY PH VALUE PRODUCT VERY SLOWLY IN 2-3 DOSES TO POOL (THIS INCLUDES ALKALINITY UP, PH UP, CAL HYPO AND LITHIUM) THE HIGH PH OF A PRODUCT IS THE CATALYST FOR A GREEN REACTION OR STAINING TO THE POOL SURFACE, NOT THE CHLORINE ITSELF.